- Remove all appendages to the North elevations to prep for replacement of cement render with lime render or feature of brickwork is possible. All appendages that are of historic value will be renovated and returned. All lights and signage will be replaced with new.
- Repair outbuilding roofs to make secure and waterproof. Repair/replace outbuilding doors and windows where necessary to secure and make waterproof.
- Replace all North elevation ground floor, first floor and second floor windows with wooden double-glazed units. Renovate external staircase.
- Renovate Hotel entrance replacing the door and windows with secure wooden door and windows.
- Replace existing uPVC guttering to the North Elevation with cast iron / aluminum guttering.



PROPOSED NORTH ELEVATION

SCALE - 1:50

