Web: www.cromwellfire.co.uk e-mail: enquiries@cromwellfire.co.uk

RSPB

Date: 3rd Dec 2020.

For the attention of: John Badley

Reference: Roads Farmhouse, Frampton Road, Boston, Lincs PE20 1AY

Re: Fire Door Survey.

With reference to our recent visit to your premise, please find the following report for your consideration.

Please see the following information.

As the building a listed building.

Location	Comments	Recommendations	Cost
Bottom of stairs to	The door has no fire	To supply and install new	
communal room.	door label, no fire door	part glazed FD30 rebate	
762mm x 1765mm	core plug and appears	door supply and install	
	hollow.	intumescent strips and	
	This door does not	cold smoke seals, fire	
	appear to be fire	rated door hinges,	
	resistant, recommend a	intumescent hinge	
	new fired door is	paper, new overhead	
	supplied and installed.	door closer and adjust.	
Bedroom 1	At present the door is a	Upgrade existing door	
805mm x 1770mm	four panelled door, not	using Envirograf	
	fire rated, some upgrade	intumescent products to	
	work appears to have	achieve 30min fire	
	been carried out, but on	rating, modify door to	
	the wrong side of the	correctly fit to frame,	
	door. Surface mounted	remove existing self-	
	intumescent strips and	adhesive strips, rebate	
	cold smoke seals has	door supply and install	
	been added to the	intumescent strips and	
	frame.	cold smoke seals, as a	
	Hinges are not fire	listed door we will need	
	resistant.	to keep the door hinges,	



















		overpaint with	
		intumescent paint, new	
		overhead door closer	
		and adjust.	
		Each door to have 1 x	
		basecoat, 2 x	
		intumescent coats and 1	
		x topcoat white finish.	
		Certificate door to a	
		nominal 30 min fire	
		door.	
Bedroom 2	At present the door is a		
		Upgrade existing door	
810mm x 1800mm	four panelled door, not	using Envirograf	
	fire rated, some upgrade	intumescent products to	
	work appears to have	achieve 30min fire	
	been carried out, but on	rating, modify door to	
	the wrong side of the	correctly fit to frame,	
	door. Surface mounted	remove existing self-	
	intumescent strips and	adhesive strips, rebate	
	cold smoke seals has	door supply and install	
	been added to the	intumescent strips and	
	frame.	cold smoke seals, as a	
	Hinges are not fire	listed door we will need	
	resistant.	to keep the door hinges,	
		overpaint with	
		intumescent paint, new	
		overhead door closer	
		and adjust.	
		and adjust.	
		Each door to have 1 x	
		basecoat, 2 x	
		intumescent coats and 1	
		x topcoat white finish.	
		Certificate door to a	
		nominal 30 min fire	
		door.	
Bedroom 3	At present the door is a	Upgrade existing door	
778mm x 1800mm	four panelled door, not	using Envirograf	
	fire rated, some upgrade	intumescent products to	
	work appears to have	achieve 30min fire	
	been carried out, but on	rating, modify door to	
	the wrong side of the	correctly fit to frame,	
	door. Surface mounted	remove existing self-	
	intumescent strips and	adhesive strips, rebate	
	cold smoke seals has	door supply and install	
	been added to the	intumescent strips and	
	frame.	cold smoke seals, as a	
	mame.	listed door we will need	
	i	iisted door we will fleed	

	Hinges are not fire resistant.	to keep the door hinges, overpaint with intumescent paint, new overhead door closer and adjust. Each door to have 1 x basecoat, 2 x intumescent coats and 1 x topcoat white finish. Certificate door to a nominal 30 min fire door.	
Living Room 785mm x 1800mm	At present the door is a four panelled door, not fire rated, some upgrade work appears to have been carried out, but on the wrong side of the door. Surface mounted intumescent strips and cold smoke seals has been added to the frame. Hinges are not fire resistant.	Upgrade existing door using Envirograf intumescent products to achieve 30min fire rating, modify door to correctly fit to frame, remove existing selfadhesive strips, rebate door supply and install intumescent strips and cold smoke seals, as a listed door we will need to keep the door hinges, overpaint with intumescent paint, new overhead door closer and adjust. Each door to have 1 x basecoat, 2 x intumescent coats and 1 x topcoat white finish. Certificate door to a nominal 30 min fire door.	
Loft Room 1 880mm x 1770mm	Current door not fire rated approximately 12mm wide, recommend supply and install a new fire door within the main frame and add new fire door stops. These doors are not suitable for upgrade works.	Install the new door within the current frame, supply and install new fire door stops. To supply and install new nonglazed FD30 rebate door supply and install intumescent strips and cold smoke seals, fire rated door hinges, intumescent hinge	

		paper, new overhead	
		door closer and adjust.	
Loft Room 2	Current door not fire	Install the new door	
650mm x 1740mm	rated approximately	within the current	
	12mm wide, recommend	frame, supply and install	
	supply and install a new	new fire door stops. To	
	fire door within the main	supply and install new	
	frame and add new fire	nonglazed FD30 rebate	
	door stops.	door supply and install	
	These doors are not	intumescent strips and	
	suitable for upgrade	cold smoke seals, fire	
	works.	rated door hinges,	
		intumescent hinge	
		paper, new overhead	
		door closer and adjust.	
Kitchen Door	Current fully glazed door	Supply and install part	
742mm 1910mm	is not fire resistant.	glazed FD30, special	
		order due to size, style	
		of glazing to be	
		confirmed.	. <u> </u>
Option 2		Supply and install new	
		nonglazed FD30 rebate	
		door supply and install	
		intumescent strips and	
		cold smoke seals, fire	
		rated door hinges,	
		intumescent hinge	
		paper, new overhead	
		door closer and adjust.	

Upon completion a NAPFIS certificate will be issued.

In answer to the question does a power opening door have to be linked to the fire alarm, the door should fail safe, that is if the mains power was cut the door could be opened from the inside with a single action without the use of a key or key code. If a magnet door lock is attached then the magnet door release will have to be connected to the fire alarm, this is to retain the single action of the means of escape. (otherwise you need to push the green box release then open the door). Hope this makes sense.

Opening of fire doors.

As there will be less than 60 persons using the exit, the door can open inwards, if opening outwards causes a problem with wind for example.

Note:

<u>230v</u>

If required a 230v supply adjacent to the fire alarm in fire resistant cable will be required at no cost to Cromwell Fire Ltd.

Exclusion

The making good of any decorative finish, damage to ceiling tiles, carpets or floors caused by removal for the sighting of detectors or the installation of cables. Full terms and conditions available upon request

Reasonable Access

Please note that it remains the customer's responsibility for the removal of all stock and obstructions, including if required furniture and carpets, which might impede the company's Engineers during the installation works.

If our Engineers have to undertake any of the above additional charges will be incurred at our standard prevailing hourly rates.

Access Equipment

If height access equipment is required, it will be provided at no cost to Cromwell Fire Ltd

Existing Equipment

Our quotation price assumes that all existing fire alarm or emergency lighting equipment that is required to be retained and reused, complete with all ancillaries and cables, are in full working order, free from any faults and fit for purpose.

Sound levels

Although every effort has been made to attain the correct decibel reading in accordance with BS5839 pt1, we cannot guarantee this until after completion. It may be necessary to add additional sounders after completion at no cost to Cromwell Fire Ltd.

Asbestos

Please notify us of any known asbestos on site before any works are undertaken. Any works regarding removal or drilling asbestos will be required to be carried out by others at no cost to Cromwell Fire Ltd.

Trunking

All trunking if used will be upvc mini trunking if any other type of trunking is required then an additional cost to cover the trunking will be charged.

Cancellations

If you cancel or postpone any orders a 10% cancellation charge will be levied against your account.

All prices quoted exclude V.A.T. this quotation will remain valid for three months.

The above quotation is subject to terms and conditions, which are available upon request.

I trust this quotation meets your approval. Should you require any further assistance please do not hesitate in contacting the undersigned?

Yours sincerely

Trevor Struggles DipFD Managing Director